

Custom order measuring and photo guide.



OR

Measuring device
or
Reference object



1. Side View



2. Screen View



1. End View



3. Case Profile View

Capture one of each angle as shown above. Try to be as close to parallel to the device as possible (small variations are fine). Use a measuring device or reference object that is universal (USA currency, card, etc.. If using a card, please cover details). Keep that reference close to the edge you are photographing. We also need one view of the case edge profile (#3). This needs to be at a slight angle so we can see the shape of the edge. If you have measurements, please include those in the message as well.